


City of Lakewood, Colorado
 Public Works Department
 Engineering Division
 303-987-7900
 www.lakewood.org



SECTION BREAKDOWN INFORMATION

Scale: 1" = 1000'



NOTE:

The 1961 BLM dependent resurvey excepted a found 1" diameter steel shaft for the center 1/4 corner, therefore I reestablished said corner at a "Broken Boundary Proportion" after consultation with Mr. Allen Arnold (BLM).

SECTION 2, TOWNSHIP 5 SOUTH, RANGE 69 WEST

DATA BY: JOHN S. LAMBERT LS #13212

DATE: Nov. 1973

BASIS OF BEARINGS: BLM 1961 survey of Sections 3 & west 1/2 of 2, T5S, R69W

Sec 2-5-69

