


City of Lakewood, Colorado
Public Works Department
Engineering Division
303-987-7900
www.lakewood.org



SECTION BREAKDOWN INFORMATION

Scale: 1" = 1000'



ANGULAR ERROR: 00°00'01.5"

AFTER THE ADJUSTMENT

LINEAR ERROR WAS 0.39' IN 21,447.53'

SECTION 8, TOWNSHIP 4 SOUTH, RANGE 69 WEST
DATA BY: Steven Steinberger and crew
FIELD DATE: Feb. 27, 1976 March 1, and 3, 1976
BASIS OF BEARINGS: Used South line of SW $\frac{1}{4}$ Sec.5,
T4S, R69W; Assumed S89°43'13"E
JOB NO. FE2676