


City of Lakewood, Colorado
Public Works Department
Engineering Division
303-987-7900
www.lakewood.org

SECTION: 4
T.5 S., R.69 W.
DATA BY: ESI
DATE: 4/30/91
JOB NO.
SCALE: 1" = 1000'

SECTION BREAKDOWN INFORMATION



Fd. 2" pipe flush on berm.
N 00°37'51" W, 76.93' from
calc'd position of S 1/4 corner
which falls in Harriman Lake.
Pipe is 1.21' west of N-S
centerline of section.

ANGULAR ERROR OF CLOSURE: 00°00'33"
LINEAR ERROR OF CLOSURE WITH NO ANGULAR ADJUSTMENT: 0.25'
TOTAL TRAVERSE LENGTH: 21,201.87'
SURVEY PRECISION: 1:85,297
THE NORTH LINE OF THE NORTHWEST ONE-QUARTER IS
ASSUMED TO BEAR N 89°13'29" E.